Customer: Machine Used: TensileTurn – Industrial Upgrade Model Date: Prepared By:

### Machined Specimens:

- C276 UNS N10276 90 HRB
- A625 UNS N06625 98 HRB
- A600 UNS N06600 88 HRB
- N200 UNS N02200 <55 HRB

#### Machining Conditions:

All parts were machined using Hysol MB10 coolant, with speeds and feeds adjusted appropriately for each material. Each part was supported using a tailstock during machining. Initial center drilling was performed on the TensileTurn – Industrial Upgrade Model using the standard center drilling program.

Note: The tailstock must be manually retracted for this operation. A 4-jaw independent chuck was essential to properly secure parts due to their irregular shapes.

### Turning Operations:

#### Operation 1:

Roughing and Finishing of the outer diameter (left side of reduced section)

- Tool: SDJCR, Radius: 0.0157"
- Insert: Kyocera DCMT11T304HQ C15 TAB08561

#### Operation 2:

Roughing and Finishing of the outer diameter (right side of reduced section)

• Tool: SDJCL, Radius: 0.0157"

## Machining Parameters:

- Surface Speed (Roughing): 800 feet/minute
- Feed per Revolution (Roughing): 0.006 inches/rev
- Surface Speed (Finishing): 800 feet/minute
- Feed per Revolution (Finishing): 0.003 inches/rev
- Depth of Cut (Radial Pass): 0.002 inches
- Cycle Time per Sample: Approximately 55 minutes
- Coolant: Hysol MB10
- Standard: ASTM E8



2220 Meridian Blvd., Suite #AF937, Minden, NV, 89423, USA
11407 SW Amu St., Tualatin, OR, 97062, USA
4071 L.B. Mcleod Rd. Ste D PMB 34, Orlando, FL, 32811, USA
847 Sumpter Road, Belleville, MI, 48111, USA
918 16 Ave NW, Calgary, AB, T2M 0K3, Canada



# SAMPLE PARTS MACHINING REPORT



#### Visual Documentation:

- A video of the machining process is available.
- Photos of finished specimens are shown below.

#### Photos of Finished Specimens:



#### C276 UNS N10276 - 90 HRB



2220 Meridian Blvd., Suite #AF937, Minden, NV, 89423, USA
11407 SW Amu St., Tualatin, OR, 97062, USA
4071 L.B. Mcleod Rd. Ste D PMB 34, Orlando, FL, 32811, USA
847 Sumpter Road, Belleville, MI, 48111, USA
918 16 Ave NW, Calgary, AB, T2M 0K3, Canada



sales@tensilemillcnc.com

# SAMPLE PARTS MACHINING REPORT



### A625 UNS N06625 - 98 HRB



A600 UNS N06600 - 88 HRB



2220 Meridian Blvd., Suite #AF937, Minden, NV, 89423, USA
11407 SW Amu St., Tualatin, OR, 97062, USA
4071 L.B. Mcleod Rd. Ste D PMB 34, Orlando, FL, 32811, USA
847 Sumpter Road, Belleville, MI, 48111, USA
918 16 Ave NW, Calgary, AB, T2M 0K3, Canada



sales@tensilemillcnc.com
 www.tensilemillcnc.com

# SAMPLE PARTS MACHINING REPORT



#### N200 UNS N02200 - <55 HRB

#### Final Notes:

- Due to the irregular shapes and material characteristics, interrupted cutting occurs frequently. A high-quality insert suitable for interrupted cutting is highly recommended.
- The machining parameters used reflect standard test conditions. However, customers are encouraged to optimize feeds, speeds, and tooling for continuous production, based on their expertise and specific performance goals.



2220 Meridian Blvd., Suite #AF937, Minden, NV, 89423, USA
11407 SW Amu St., Tualatin, OR, 97062, USA
4071 L.B. Mcleod Rd. Ste D PMB 34, Orlando, FL, 32811, USA
847 Sumpter Road, Belleville, MI, 48111, USA
918 16 Ave NW, Calgary, AB, T2M 0K3, Canada

